

Mitigation Summary of Objects

The Mitigation Summary tab provides an overview of the mitigation and verification status of all objects identified.

There are 2 sub tabs Object Information, Mitigation Information in Mitigation Summary.

Object Information

Object information sub tab has the following information with penetration amount, MSL, latitude and longitude.

Object Information		Mitigation Information				
Object Identifier	Object Type	Runway End Designator	Penetration Amount	MSL	Latitude	Longitude
55-AIRPORTSGIS-636776	AERIAL CABLEWAY	07	150.27 feet	1258.59 feet	N 45 18 30.33	W 91 38 52.45
55-081737	TREE	17	16.49 feet	1144 feet	N 45 18 46.94	W 91 38 13.11
55-053674	TREE	17	12.5 feet	1141 feet	N 45 18 47.13	W 91 38 13.21
55-054192	TREE	25	47.31 feet	1147 feet	N 45 18 31.71	W 91 37 59.58
55-081278	TREE	25	44.46 feet	1145 feet	N 45 18 32.70	W 91 37 59.71
55-054195	TREE	25	3.25 feet	1104 feet	N 45 18 34.32	W 91 38 0.27
55-053819	TREE	25	7.64 feet	1179 feet	N 45 18 35.71	W 91 37 40.33
55-066282	TREE	25	27.27 feet	1127 feet	N 45 18 36.65	W 91 38 1.46
55-053340	TREE	25	22.01 feet	1116 feet	N 45 18 37.22	W 91 38 3.34
55-053341	TREE	25	42.24 feet	1139 feet	N 45 18 37.38	W 91 38 2.60
55-052841	TREE	25	38.66 feet	1138 feet	N 45 18 37.69	W 91 38 1.97
55-065948	TRAVERSE_WAY	35	4.32 feet	1068 feet	N 45 17 59.98	W 91 38 2.53
55-079854	TRAVERSE_WAY	35	4.4 feet	1068 feet	N 45 17 59.98	W 91 38 2.78

Mitigation Information

This tab is for ODT team to complete and enter the details so Airport Sponsor can request FAA to return the service.

Object Information		Mitigation Information						
Object Identifier	Compliance Plan Status	Mitigation Request Status	Mitigation Completion Date	FAA Database Updated	FAA Database Updated Date	Verification	Comment	New MSL
55-AIRPORTSGIS-636776	Completed Filed Mitigation Request	Completed	Tue, 14 Aug 2018			Valid		
55-081737	Not Valid - Removed	N/A				Not Valid	Object is removed from that location and is not penetrating anymore	
55-053674	Not Valid - Lowered (Click to see the uploaded files)	N/A				Not Valid	Object is lowered to reduce penetration	1108 feet
55-054192	Not Valid - Not In FAA Provided List	N/A		No Action		Not Valid	Object is not in the list provided by FAA to mitigate	
55-081278	Lowered (Click to see the uploaded files)	N/A	Wed, 15 Aug 2018			Valid	Object will be lowered to reduce penetration	954 feet
55-054195	Removed	N/A	Sun, 12 Aug 2018			Valid	Object no longer exists	
55-053819	Removed	N/A	Tue, 7 Aug 2018			Valid	Object no longer exists	
55-066282	Lit	N/A	Fri, 17 Aug 2018			Valid	object lighting helps the planes to land	
55-053340	Lit	N/A	Sun, 12 Aug 2018			Valid	object lighting helps the planes to land	
55-053341	No Action	N/A	Wed, 8 Aug 2018			Valid	The object is not penetrating and is outside the surface.	
55-052841	No Action	N/A	Fri, 10 Aug 2018			Valid	The object is not penetrating and is outside the surface.	
55-065948	No Action	N/A	Mon, 6 Aug 2018			Valid	No action on these objects	
55-079854	No Action	N/A	Sat, 11 Aug 2018			Valid	No action on these objects	

ODT Login

Login as ODT with permissions to update the FAA Database Updated and FAA Database Updated Date.

Object Information		Mitigation Information						
Object Identifier	Compliance Plan Status	Mitigation Request Status	Mitigation Completion Date	FAA Database Updated	FAA Database Updated Date	Verification	Comment	New MSI
55-AIPORTSGIS-636776	Completed Filed Mitigation Request	Completed	Tue, 14 Aug 2018	<input type="text" value=""/>	<input type="text" value=""/>	Valid		
55-081737	Not Valid - Removed	N/A		<input type="text" value=""/>	<input type="text" value=""/>	Not valid	Object is removed from that location and is not penetrating anymore	
55-053674	Not Valid - Lowered (Click to see the uploaded files)	N/A		<input type="text" value=""/>	<input type="text" value=""/>	Not valid	Object is lowered to reduce penetration	1108 feet
55-054192	Not Valid - Not In FAA Provided List	N/A		No Action ▾	<input type="text" value=""/>	Not Valid	Object is not in the list provided by FAA to mitigate	
55-081278	Lowered (Click to see the uploaded files)	N/A	Wed, 15 Aug 2018	<input type="text" value=""/>	<input type="text" value=""/>	Valid	Object will be lowered to reduce penetration	954 feet
55-054195	Removed	N/A	Sun, 12 Aug 2018	<input type="text" value=""/>	<input type="text" value=""/>	Valid	Object no longer exists	
55-053819	Removed	N/A	Tue, 7 Aug 2018	<input type="text" value=""/>	<input type="text" value=""/>	Valid	Object no longer exists	
55-066282	Lit	N/A	Fri, 17 Aug 2018	<input type="text" value=""/>	<input type="text" value=""/>	Valid	object lighting helps the planes to land	
55-053340	Lit	N/A	Sun, 12 Aug 2018	<input type="text" value=""/>	<input type="text" value=""/>	Valid	object lighting helps the planes to land	
55-053341	No Action	N/A	Wed, 8 Aug 2018	<input type="text" value=""/>	<input type="text" value=""/>	Valid	The object is not penetrating and is outside the surface.	
55-052841	No Action	N/A	Fri, 10 Aug 2018	<input type="text" value=""/>	<input type="text" value=""/>	Valid	The object is not penetrating and is outside the surface.	
55-065948	No Action	N/A	Mon, 6 Aug 2018	<input type="text" value=""/>	<input type="text" value=""/>	Valid	No action on these objects	
55-079854	No Action	N/A	Sat, 11 Aug 2018	<input type="text" value=""/>	<input type="text" value=""/>	Valid	No action on these objects	

[Save FAA Database Update Data](#)

All objects marked as Not Valid in Verification tab and objects from Compliance Plan are displayed here.

Objects marked as Not in FAA Provided List are defaulted to No Action and not required to select the date for FAA Database Updated Date.

55-054192	Not Valid - Not In FAA Provided List	N/A		No Action ▾	<input type="text" value=""/>	Not Valid	Object is not in the list provided by FAA to mitigate	
-----------	--------------------------------------	-----	--	-------------	-------------------------------	-----------	---	--

Objects marked as Not Valid are displayed with prefix Not Valid under Compliance Plan Status.

55-081737	Not Valid - Removed	N/A		<input type="text" value=""/>	<input type="text" value=""/>	Not Valid	Object is removed from that location and is not penetrating anymore	
55-053674	Not Valid - Lowered	N/A		<input type="text" value=""/>	<input type="text" value=""/>	Not valid	Object is lowered to reduce penetration	1108 feet
55-054192	Not Valid - Not In FAA Provided List	N/A		No Action ▾	<input type="text" value=""/>	Not Valid	Object is not in the list provided by FAA to mitigate	

Click on Filed Mitigation Request to view the Mitigation Request form

Object Identifier	Compliance Plan Status	Mitigation Request Status	Mitigation Completion Date	FAA Database Updated	FAA Database Updated Date	Verification	Comment	New MSL
55-AIRPORTSGS-752280	Completed Filed Mitigation Request	Completed	Tue, 14 Aug 2018	<input type="text"/>	<input type="text"/>	Valid		

Click on Click to see the uploaded files to view any files uploaded.

55-081278	Lowered (Click to see the uploaded files)	N/A	Wed, 15 Aug 2018	<input type="text"/>	<input type="text"/>	Valid	Object will be lowered to reduce penetration	954 feet
-----------	---	-----	------------------	----------------------	----------------------	-------	--	----------

Date is not required if FAA Database Updated is selected as No Action.

Object Identifier	Compliance Plan Status	Mitigation Request Status	Mitigation Completion Date	FAA Database Updated	FAA Database Updated Date	Verification	Comment	New MSL
55-AIRPORTSGS-636776	Completed Filed Mitigation Request	Completed	Tue, 14 Aug 2018	Completed ▾	Thu, 16 Aug 2018	Valid		
55-081737	Not Valid - Removed	N/A		Completed ▾	Wed, 08 Aug 2018	Not Valid	Object is removed from that location and is not penetrating anymore	
55-053674	Not Valid - Lowered (Click to see the uploaded files)	N/A		Completed ▾	Wed, 15 Aug 2018	Not Valid	Object is lowered to reduce penetration	1108 feet
55-054192	Not Valid - Not In FAA Provided List	N/A		No Action ▾		Not Valid	Object is not in the list provided by FAA to mitigate	
55-081278	Lowered (Click to see the uploaded files)	N/A	Wed, 15 Aug 2018	Completed ▾	Sat, 18 Aug 2018	Valid	Object will be lowered to reduce penetration	954 feet
55-054195	Removed	N/A	Sun, 12 Aug 2018	Completed ▾	Wed, 15 Aug 2018	Valid	Object no longer exists	
55-053819	Removed	N/A	Tue, 7 Aug 2018	Completed ▾	Fri, 10 Aug 2018	Valid	Object no longer exists	
55-066282	Lit	N/A	Fri, 17 Aug 2018	Completed ▾	Tue, 21 Aug 2018	Valid	object lighting helps the planes to land	
55-053340	Lit	N/A	Sun, 12 Aug 2018	Completed ▾	Mon, 20 Aug 2018	Valid	object lighting helps the planes to land	
55-053341	No Action	N/A	Wed, 8 Aug 2018	No Action ▾	<input type="text"/>	Valid	The object is not penetrating and is outside the surface.	
55-052841	No Action	N/A	Fri, 10 Aug 2018	No Action ▾	<input type="text"/>	Valid	The object is not penetrating and is outside the surface.	
55-065948	No Action	N/A	Mon, 6 Aug 2018	No Action ▾	<input type="text"/>	Valid	No action on these objects	
55-079854	No Action	N/A	Sat, 11 Aug 2018	Completed ▾	Wed, 15 Aug 2018	Valid	No action on these objects	

[Save FAA Database Update Data](#)

After entering data for objects in FAA Database updated and FAA Database Update Date, Click on Save FAA Database Update Data to save the data. The following popup is displayed.

Do you want to save changes to FAA Database Update(s)?

Click Yes. Data is saved.

After all objects are set as either Completed or No Action, Request FAA Return Service or Capability will be enabled.

Email is sent to Airport sponsor and assigned consultant and are notified that they can request Night services.

Airport Sponsor/Consultant Request FAA Return Service

Login as Airport sponsor or assigned consultant. Click on Surface Analysis and Visualization from dashboard. Enter the airport and click Submit.

Click on Mitigation Summary and then Mitigation Information.

Object Identifier	Compliance Plan Status	Mitigation Request Status	Mitigation Completion Date	FAA Database Updated	FAA Database Updated Date	Verification	Comment	New MSL
55-AIRPORTSGS-636776	Completed Filed Mitigation Request	Completed	Tue, 14 Aug 2018	Completed	Thu, 15 Aug 2018	Valid		
55-081737	Not Valid - Removed	N/A		Completed	Wed, 8 Aug 2018	Not valid	Object is removed from that location and is not penetrating anymore	
55-053674	Not Valid - Lowered (Click to see the uploaded files)	N/A		Completed	Wed, 15 Aug 2018	Not valid	Object is lowered to reduce penetration	1108 feet
55-054192	Not Valid - Not In FAA Provided List	N/A		No Action		Not valid	Object is not in the list provided by FAA to mitigate	
55-081278	Lowered (Click to see the uploaded files)	N/A	Wed, 15 Aug 2018	Completed	Sat, 18 Aug 2018	Valid	Object will be lowered to reduce penetration	954 feet
55-054195	Removed	N/A	Sun, 12 Aug 2018	Completed	Wed, 15 Aug 2018	Valid	Object no longer exists	
55-053819	Removed	N/A	Tue, 7 Aug 2018	Completed	Fri, 10 Aug 2018	Valid	Object no longer exists	
55-066282	Lit	N/A	Fri, 17 Aug 2018	Completed	Tue, 21 Aug 2018	Valid	object lighting helps the planes to land	
55-053340	Lit	N/A	Sun, 12 Aug 2018	Completed	Mon, 20 Aug 2018	Valid	object lighting helps the planes to land	
55-052341	No Action	N/A	Wed, 8 Aug 2018	No Action		Valid	The object is not penetrating and is outside the surface.	
55-052841	No Action	N/A	Fri, 10 Aug 2018	No Action		Valid	The object is not penetrating and is outside the surface.	
55-065948	No Action	N/A	Mon, 6 Aug 2018	No Action		Valid	No action on these objects	
55-079854	No Action	N/A	Sat, 11 Aug 2018	Completed	Wed, 15 Aug 2018	Valid	No action on these objects	

Click on Request FAA Return Service or Capability and the following popup is displayed.

Please indicate why you are requesting the FAA to return service:

Mitigation of all FAA identified 20:1 Obstacle Penetrations are complete:

[Send Request](#) [Cancel](#)

Select the checkbox and click Send Request.

An email is sent to FAA with the request from airport sponsor or assigned consultant to return the service or capability.